



3D METAL MODEL KITS

B-24 Liberator



Metal sheets

Same color parts on the right are duplicates



In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed

Legends:

E Engraved/Color side

NE Non-engraved/Silver side


Attention point

● Insert tab and bend 90 degrees

○ Insert tab and twist 90 degrees

Assembly tip:

If needed, slightly twist tabs to hold parts together, then untwist and bend them down for a nice finish




Recommended tools:


-Wire cutters: helpful for taking parts from the metal sheets.

















-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.



Assembly Flow Chart





Insert the blue holes firstly, then insert the red holes.

Insert the blue holes firstly, then insert the red holes.

